










Paso 3,5mm	Paso 5,08mm	
Resorte push-in	Tornillo	Resorte push-in
 <p data-bbox="97 644 419 711">DFMC 1,5/...-ST-3,5-LR 2-20 polos</p>	 <p data-bbox="596 644 935 711">MSTB 2,5/...-ST-5,08-LR 2-20 polos</p>	 <p data-bbox="1043 644 1362 711">FKC 2,5/...-ST-5,08-LR 2-20 polos</p>
 <p data-bbox="97 954 544 1021">DMC 1,5/...-G1F-3,5-LR P20THR 2-20 polos</p>	 <p data-bbox="596 954 943 1021">MSTBA 2,5/...-G-5,08-LR 2-20 polos</p>	 <p data-bbox="1043 954 1469 1021">CC 2,5/...-GF-5,08-LR P26THR 2-12 polos</p>
 <p data-bbox="97 1233 560 1300">DMCV 1,5/...-G1F-3,5-LR P20THR 2-20 polos</p>	 <p data-bbox="596 1233 963 1300">MSTBVA 2,5/...-G-5,08-LR 2-20 polos</p>	 <p data-bbox="1043 1233 1490 1300">CCV 2,5/...-GF-5,08-LR P26THR 2-12 polos</p>